				-	Section 1	National Park	Meeting			
		M	7	YES L	2:25	3-17-16	Setup FAIR Training	ω 4 т		
	Notes		Mtrl Check Rev Letter	Approved N Yes/No Ch	Time Of Day	Date Part Submitted	Maintenance Tooling	2 1		
		Inspection Record	First Part			S	Down Time Codes	ctions	Special Notes / Instructions	Specia
				Manager of the State of the Sta			al			ROUTING:
	*									
	(
	3155		æ							
	1/0									
						1				
		F.								
									(1 7.7
						ال	<u>ئ</u>	HDm()	ノこ	3/17///
ap Scrap	Scrap	Notes		Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date /
	put/8hrs		109/11		Time	Hrs.	н			
	Thru-		Doc /Ur		Cycle	Setup	Se		Mach No	
				L			Do not require traceability.	Do not requir	Caps/Plugs	Сар
					•=	y "Lot Number	Located on the bag followed by "Lot Number."	Located on th	Snap Rings	Sna
					e box label.	and date on the	Use their work order number and date on the box label	Use their wor	Flare Tubes	- Flare
					letter "M."	arting with the I	Located on the spool label, starting with the letter "M."	Located on th	Copper Tubing	Coppe
		CP15			word "heat."	ctly above the v	Located on the box label, directly above the word "heat."	Located on th	Brazing Rings	Brazi
		BRZ09			ox quantity.	x label under b	Six digit no. located on the box label under box quantity.	Six digit no. l	Flare Nuts	Flar
		CUTU-1-7/8				Numbers	Distinguishing Traceablity Numbers	Distinguis		
		SF704-20-3/16	SF				0	20	Order Qty	Ord
	No(s)	Component(s)	- 0	TC	devices, LLC	Ŧ	594	404594	Order No.	Ord
	Heat Lot/Traceability				1		0-3/16	5704-20-3/16	Part No.	Pa