Part No.	1102-1	1102-14-5/16-R			7		_			Heat Lot/Traceability	ility	
Order No.	39	399707		A	devices, LLC	LC		Com	omponent(s)	No(s)		
Order Qty		12						110	1102-14-5/16	N/N		
	Distingu	Distinguishing Traceablity Numbers	lity Numb	ers					C-RING	N/A		
Flare Nuts	Six digit no.	Six digit no. located on the box label under box quantity.	box labe	l under bo	ox quantity.							
Brazing Rings	Located on	Located on the box label, directly above the word "heat."	directly ak	ove the v	vord "heat."							
Copper Tubing	Located on	Located on the spool label, starting with the letter "M."	, starting	with the l	etter "M."							
Flare Tubes	Use their w	Use their work order number and date on the box label.	per and d	ate on the	box label.							
Snap Rings	Located on	Located on the bag followed by "Lot Number."	ed by "Lot	t Number	-							
Caps/Plugs	Do not requ	Do not require traceability.										
			Control of the last of the las									
Mach. No.			Setup Hrs.		Cycle Time			Pcs./Hr		Thru- put/8hrs		
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum.	Cum. Total	Down Time	Down Time Code			Notes		Scrap	Scrap Code
9/s 8/r		(A)										
										ALD OIL		
									7	1		
					_				1	Ú		
											D	
ROUTING:												
Special Notes / Instructions	ıctions	Down Time Codes	odes	S. Santida				First Part In	Inspection Record			
		 Maintenance Tooling 		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev Letter	Inspector	Notes		
		4 FAIR 5 Training										
		2012015										
BRAZING PRODUCTION RECORD	ORD										Test F	Test Form 11/4/15