Test Form 11/4/15	Test										RD	BRAZING PRODUCTION RECORD	BRAZING PRO
			-										
			,	+		,		,		4 FAIR 5 Training			
		#090m)	27	}	1	URI	9:30	11/12/11					
	Notes	600	Inspector	Rev Letter	Check	Approved Yes / No	Time Of Day	Date Part Submitted					
		Market Bar	First Part Inspection Record	First Part Ir					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
	C												ROUTING:
	Þ												20
										-			
		0											
		3	てい										
	-	1	1 3										2
		5											
								1					
													, /
								min	30	30		CS	11/12/15
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs			100 och		Time		Hrs.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
				Special control of	MCIENTE STORY			Street of State Street					
									У.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
							=	ot Number.	red by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
							box label.	date on the	ber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
							etter "M."	g with the k	l, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
			CP15		L .		ord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
			BRZ09		I		x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
			CUTU-0-7/8	כר				nbers	olity Num	Distinguishing Traceablity Numbers	Distingu		
			F704-20-3/16	SF7						30		Order Qty	Ord
	No(s)		component(s)	Cor		ררכ	devices, LLC	H		390184	39	Order No.	Ord
	Heat Lot/Traceability	Heat Lot		,			7			S704-20-3/16	S704-	Part No.	Par