								66.0	1			
								o	3 Setup 4 FAIR 5 Training			
	Notes	Inspector	-	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	enance				
		Inspection Record	First Part I					Time Codes	Down Time	ctions	Special Notes / Instructions	Specia
8	_											ROUTING:
P	2											
	S.					#						
	21/6											
	0 11 1					•						
	5											
								+				
									エ		SB	126
Scrap Scrap		Notes			Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
									Service and the service and th	- Personal P	STATE OF THE PARTY	
							Do not require traceability.	ability.	uire trace	Do not require traceability.	Caps/Plugs	Caps
						יי איני ומהבוי	ose their work order hallinger and date on the box laber.	ב וועוווטכו מוו	VOIN OI GE	י איירין איי	Binas	6 6
						etter M.	lse their work order number and date on the boy label	r niimher an	work order	Located or	Flare Tubes	Flare
						vord "heat."	ocated on the box label, directly above the word "heat."	label, directi	n the box I	Located or	Brazing Rings	Brazir
	20263300	A-RING				ox quantity.	Six digit no. located on the box label under box quantity.	on the box l	o. located	Six digit no		Flare
	AIN	A40					ımbers	Distinguishing Traceablity Numbers	uishing Tr	Disting		
	397999	1304-33-1/4	13						4		Order Qty	Orde
	No(s)	Component(s)	Cor		LLC	devices, LLC	THE STATE OF THE S		398020	3	Order No.	Ord
<u> </u>	Heat Lot/Traceability		,			7						