133 ARU

				Service Control of the last	THE REAL PROPERTY OF THE PARTY	Wildern source	Meeting	6 2		
							Training			
		Alle		YES / NO CHECK		2-24-15	Setup	4 & 4 - S - T		
	Notes	Inspector	Rev Let		Time Of Day Ap	Date Part	Maintenance			
		rt Inspection Record	First Part I				Down Time Codes		Special Notes / Instructions	Special
				The second second						ROUTING:
R										
\										
	100									
	5			+						
	3									
7					+	1 23	1	<i>(</i> ; <i>)</i>	(10/04/12
3					3	164	120	£€		
Scrap Scrap		Notes		Down Time Code	Down Time Do	Cum. Total	Total Pcs.	Prod Hrs. T	Emp. Name	Date
	put/8hrs		1,000,11		Time		Hrs.			
	Thru-		Pcs./Hr		Cycle	ס	Setup		Mach. No.	
		CP13					traceability.	Do not require traceability.	Caps/Plugs [Caps,
		L-RING				"Lot Number."	Located on the bag followed by "Lot Number."	ocated on the		Snap
		BRZ03			box label.	nd date on the	Use their work order number and date on the box label.	se their work	Flare Tubes	Flare
		CUTU-1.875-1/2	CUT		etter "M."	ting with the le	Located on the spool label, starting with the letter "M."	ocated on the	Copper Tubing L	Copper
		BRZ04			ord "heat."	ly above the w	Located on the box label, directly above the word "heat."	ocated on the	Brazing Rings L	Brazin
		CUTU-17-3/16	CU		x quantity.	label under bo	Six digit no. located on the box label under box quantity.	ix digit no. loca	Flare Nuts	Flare
		П				umbers	Distinguishing Traceablity Numbers	Distinguishi		
	394325	SF403-3-3/16	SF					650	Order Qty	Orde
	No(s)	Component(s)	6		devices, LLC	1	5	394325	Order No.	Orde
Υ	Heat Lot/Traceability		-		25170	J	1/1-1/1	יידידים לכככיים	140.	rait ivo.