Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
		Notes	Inspector	Rev Letter	Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted	ice	<ol> <li>Maintenance</li> <li>Tooling</li> </ol>			
			First Part Inspection Record	First Part I					ne Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	Z									,			
	5												
		5											
		020											
		200				9.							
		at "	B		5								
	(												
								1					
										S		56	3/36
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	0	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Section Services	70110		No. of the last of	A STATE OF THE PARTY OF THE PAR					Carlo State Control State Control			
		Thru-		Pcs./Hr			Cycle	ס	Setup			Mach. No.	
									lity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
							=	Located on the bag followed by "Lot Number."	wed by	the bag folic	Located on	Snap Rings	Snap
							box label.	Use their work order number and date on the box label.	mber an	ork order nu	Use their w	Flare Tubes	Flare
							etter "M."	Located on the spool label, starting with the letter "M."	bel, starti	the spool lal	Located on	Copper Tubing	Coppe
							vord "heat."	Located on the box label, directly above the word "heat."	directly	the box labe	Located on	Brazing Rings	Brazir
		NA	G-RING	500			x quantity.	Six digit no. located on the box label under box quantity.	the box la	located on t	Six digit no.	Flare Nuts	Flar
		N/A	G6					mbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
		109104	702-8-1/4	7	li 					5		Order Qty	Ord
		No(s)	Component(s)	COL		LLC	devices, LLC	4		402081	40	Order No.	Ord
	ity	Heat Lot/Traceability	20000+(5)				ontrol			702-8-1/4-6	702-	Part No.	Par