										6 Meeting			
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 			
		р	First Part Inspection Record	First Part Ir					Codes	Down Time Codes	tions	Special Notes / Instructions	Special
													ROUTING:
	P												
			1										
	j.)											
	7												
												1	
								1					
H										30		56	2/17
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs	Th put/		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
									, y	Do not require traceability.	Do not requ	Caps/Plugs	Caps
					•			ot Number.	ved by "Lo	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
							box label.	date on the	ber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
							etter "M."	g with the le	el, starting	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
							ord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazin
	8						x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
	30060667		E-RING					bers	blity Num	Distinguishing Traceablity Numbers	Distingu		
	CA	_	901-9-1/4	9						20		Order Qty	Orde
	No(s)		Component(s)	Con		LC	devices, LLC	4		400899	40	Order No.	Orde
	Heat Lot/Traceability	I)			Ó T			9U1-9-1/4-K	-TOE	rait No.	Par