										Training Meeting	6 5		
											8 4		
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	S. 191		2 1		
			Inspection Record	First Part Ir					Codes	Down Time Codes	tions	Special Notes / Instructions	Special
													ROUTING:
	P												
		5.50											
		505											
		28											
		5		1									
											a.		
										t		S	12/21
Scrap	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					Time		Hrs.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
									ļ ķ	Do not require traceability.	o not requ	Caps/Plugs [Caps/
							=	ot Number.	ved by "L	Located on the bag followed by "Lot Number."	ocated on	Snap Rings	Snap
							box label.	date on the	nber and	Use their work order number and date on the box label.	Jse their wo	Flare Tubes	Flare
							etter "M."	g with the l	el, startin	Located on the spool label, starting with the letter "M."	ocated on	Copper Tubing L	Copper
							vord "heat."	above the v	directly	Located on the box label, directly above the word "heat."	ocated on	Brazing Rings	Brazin
		Z/A	A-KF003				ox quantity.	oel under bo	ıe box lak	Six digit no. located on the box label under box quantity.	ix digit no.	Flare Nuts	Flare
		N/A	DCN516-HT	D				nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
		016762	2803-8-1/4-0	28						4		Order Qty	Orde
		No(s)	Component(s)	Cor		LLC	devices, LLC	H		394910	39	Order No.	Orde
	ility	Heat Lot/Traceability)			1			2803-8-1/4	2002		1 01