Test Form 11/4/15	Test Fo								Ö	BRAZING PRODUCTION RECORD	BRAZING PROD
								Meeting	6 U		
		9 30		T'	7			FAIR			
		Unse 09	#	7	ines	GAN	1-25-16	Setup			
		Notes	Inspector	Mtrl Rev Letter	Approved N Yes / No Ch	Time Of Day	Date Part Submitted	Maintenance Tooling	2 To		
	- Stells		Inspection Record	First Part	Н			Down Time Codes		Special Notes / Instructions	Special I
											ROUTING:
					-						
						1	((10%
	0					B)	Ź	Y	(MED)MIN	500	1/28/
Scrap Code	Scrap		Notes		Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs. To	Emp. Name	Date
		put/8nrs				lime	s.	Hrs.			
	- 1.00	Thru-		Pcs./Hr		Cycle	d d	Setup		Mach. No.	
								aceability.	Do not require traceability.	.1	Caps/Plugs
							Located on the bag followed by "Lot Number."	ag followed by	cated on the k		Snap Rings
		34 34 34	CP14			box label.	Use their work order number and date on the box label.	rder number a	se their work o		Flare Tubes
		133173	BRZ22			etter "M."	Located on the spool label, starting with the letter "M."	pool label, star	cated on the s		Copper Tubing
		134625	BRZ07			ord "heat."	Located on the box label, directly above the word "heat."	ox label, direc	cated on the k	,	Brazing Rings
		٠٨٠	TU-36-5/32-B	сит		x quantity.	Six digit no. located on the box label under box quantity.	ted on the box	x digit no. loca		Flare Nuts
		٧	CSW-3-5/8	33			lumbers	Distinguishing Traceablity Numbers	Distinguishin		
		٧.	SF5-2.5-15	1S	l)		÷.		3	Qty	Order Qty
		No(s)	Component(s)	Con	CC	devices, LLC	4		398401	No.	Order No.
	lity	Heat Lot/Traceability	anomat(c)			ontrol	1	6-B	S5-2.5-15-36-B	No.	Part No.
		20									