							Meeting	6 0		
							Setup FAIR Training	ω 4 π		
	Notes	Inspector		Approved Mtrl Yes / No Check	Time Of Day Ap	Date Part Submitted	Maintenance Tooling	2		
		First Part Inspection Record	First Part I				Down Time Codes	tions	Special Notes / Instructions	Specia
										ROUTING:
Ø										
	,			-						
	1215									
	7.1									
	5/									
							0	NIW CI	9	11/30
Code				5				\ I	70	13.
Scrap Scrap		Notes		Down Time	Down Time Do	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs		Pcs./Hr		Time	- 6	Hrs.		Mach. No.	
					が 大学 中では 日本は ままい		2	NAME OF TAXABLE PARTY.	September Control	
							e traceability.	Do not require traceability.	Caps/Plugs	Cap
					-	"Lot Number.'	Located on the bag followed by "Lot Number."	ocated on th	Snap Rings	Snaj
					box label.	າd date on the	Use their work order number and date on the box label.	Jse their wor		Flare
					etter "M."	ting with the le	Located on the spool label, starting with the letter "M."	ocated on th	Copper Tubing	Coppe
	,	CP14			ord "heat."	ly above the w	Located on the box label, directly above the word "heat."	ocated on th	Brazing Rings	Brazi
	N/A	BRZ07	×		x quantity.	abel under bo	Six digit no. located on the box label under box quantity.	six digit no. lo	Flare Nuts	Flar
	N/A	CUTU-0-5/8	CI			umbers	Distinguishing Traceablity Numbers	Distinguis		
	186168	ASC-9						6	Order Qty	Ord
5	No(s)	component(s)	<u></u>	.,	devices, LLC	4	87	391787	Order No.	Ord
lity	Heat Lot/Traceability	manat (c)	2				9-5	ASC-9-5	Part No.	Pai