Test Form 11/4/15	Ţ							a.			ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	'n	 Maintenance Tooling 			
			rt Inspection Record	First Part In					e Codes	Down Time Codes	ctions	Special Notes / Instructions	Speci
													ROUTING:
	8												
	10												
	Z												
	2												
	7												
				100									
			1										
										9		56	1/20
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Ct	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Thru- put/8hrs		Pcs./Hr		0	Cycle Time		Setup Hrs.		4	Mach. No.	
			THE RESERVE OF THE PERSON NAMED IN			· · · · · · · · · · · · · · · · · · ·							
									ty.	Do not require traceability.	Do not requ	Caps/Plugs	Cap
							Ē	Lot Number.	wed by "	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
					1		box label.	date on the	nber and	Use their work order number and date on the box label	Use their w	Flare Tubes	Flan
							etter "M."	ng with the I	el, starti	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
					<u></u>		vord "heat."	above the v	, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
							ox quantity.	bel under bo	he box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
	NA	2	DCN516-HT	DC				mbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
	396632	396	2803-14-3/16-0	2803	ii					9		Order Qty	Ord
	No(s)		component(s)	Con		LLC	devices, LLC	H		397585	39	Order No.	Orc
	Heat Lot/Traceability	Heat Lo								2803-14-3/16	2803-	Part No.	Pa
													1