Test Form 11/4/15	Test F									ORD	BRAZING PRODUCTION RECORD	BRAZING PR
									Meeting			
			705	#	9	N=V	C126-	-12-16		л 4. п		
	tes	Notes	Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted		3 2 L		
			First Part Inspection Record	First Part In							Special Notes / Instructions	Specia
												ROUTING:
	4											
		5	775									
		1	- 17									
1												
								000	ourses	SIMILA		11411
Code						code		<i>y</i>	<u>ر</u>	3		1/10/11
Scrap	Scrap		Notes			Down Time	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					Time	S.	Hrs.			
		Thru-		Pcs./Hr			Cycle	dn	Setup		Mach. No.	
									Do not require traceability.	Do not requ	Caps/Plugs	cap
								"Lot Number.	Located on the bag followed by "Lot Number."	Located on t		Snaı
							box label.	nd date on the	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
							etter "M."	ting with the I	Located on the spool label, starting with the letter "M."	Located on t	Copper Tubing	Coppe
			CP13				vord "heat."	tly above the v	Located on the box label, directly above the word "heat."	Located on t	Brazing Rings	Brazi
			CUTU-1-1/2	CU		ăŭ.	ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
			BRZ03					lumbers	Distinguishing Traceablity Numbers	Distingui		
	~	242242	F405-2-1/4-1/2	SF40			2		20		Order Qty	Ord
9		No(s)	Component(s)	Con		LC	devices, LLC	THE STATE OF THE S	396643	396	Order No.	Ord
	ability	Heat Lot/Traceability		,					S405-2-1/4-1/2	S405-2	Part No.	Pa