									6 Meeting			
										10.5		
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted		<ol> <li>Maintenance</li> <li>Tooling</li> <li>Setup</li> </ol>	(a. ba.		
		rt Inspection Record	First Part Ir					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
(												ROUTING:
I	M											
)	(200)											
	るがじ											
	5											
			20									
ı												
	197									*		
									£		SB	iay,
Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
								Total Section 1			A STORY OF THE STREET	
								×.	Do not require traceability.	Do not requ	Caps/Plugs	Cap
				<b>.</b>		-	ot Number.'	red by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
						box label.	date on the	ber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	g with the le	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						ord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
						x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
	30060667	E-RING					bers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
	N/A	ER15		lii E					4		Order Qty	Ord
	No(s)	Component(s)	Con		LLC	devices, LLC	7		392241	39	Order No.	Ord
lity	Heat Lot/Traceability		)			2			EKID-K	בא	rait NO.	Ра