									5 Training 6 Meeting			
	Notes	Inspector	Rev Letter		Yes / No	Time Of Day			2 Tooling 3 Setup			
		First Part Inspection Record	FIRST Part In	Mtri	Approved		Date Part	Codes	1 Maintenance		opecial Notes / Histinctions	Special
								0	Down Times	tions.	Notos (Instance	Canada
												ROUTING:
	30											
	(****										
_	S.											
\parallel	110/10									×		
	,											
	£											
									8		ليلا	d/ 1/10
Scrap Code	Scrap	Notes			Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
								Υ.	Do not require traceability.	Do not requ	Caps/Plugs L	Caps,
							ot Number.	ved by "Lc	Located on the bag followed by "Lot Number."	ocated on		Snap
						box label.	date on the	nber and c	Use their work order number and date on the box label.	Use their w		Flare
						etter "M."	with the le	el, starting	Located on the spool label, starting with the letter "M."	ocated on	Copper Tubing L	Copper
7	-					ord "heat."	bove the w	directly a	Located on the box label, directly above the word "heat."	ocated on	Brazing Rings L	Brazin
18	2) A	G-RING	6			x quantity.	el under bo	e box labe	Six digit no. located on the box label under box quantity.	six digit no.	Flare Nuts S	Flare
67	393934	G6	*(4)				bers	blity Numi	Distinguishing Traceablity Numbers	Distingu		
	398956	702-8-1/4	70						8		Order Qty	Orde
	No(s)	component(s)	Com		LLC	devices, LLC	1		400688	40	Order No.	Orde
	Heat Lot/Traceability	nonont(c)	Com			ontrol			702-8-1/4-6	702-	Part No.	Part