								ora o	6 Meeting			
								R				
								9				
				\dashv			100 mm (mm) (mm) (mm) (mm) (mm) (mm) (mm)					
	Notes	Inspector	Rev Letter	ed Mtrl Check	Approved / Yes / No	Time Of Day	Date Part Submitted	nance	1 Maintenance			
		rt Inspection Record	First Part I		A STATE			Down Time Codes	Down	ctions	Special Notes / Instructions	Specia
												ROUTING:
4	×											
	33.50											
	0 5 4 0											
1												
			ä									
									6		56	4/10
0000												
Scrap Scrap	Sc	Notes		ne	Down Time	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
	bay om s					IIIIe	-	nis.				
	Thru-		Pcs./Hr			Cycle	ਰ	Setup			Mach. No.	
TOTAL STATES			STATE STREET, ST.			PERSONA STREET	TENNE CHARGO		Contraction			
								ability.	uire tracea	Do not require traceability.	K	Caps
						· a	Located on the bag followed by "Lot Number."	ollowed by	the bag fo	Located on	Snap Rings	Snap
i						box label.	Use their work order number and date on the box label	number an	ork order	Use their w	Flare Tubes	Flare
						etter "M."	Located on the spool label, starting with the letter "M."	label, start	the spool	Located on	Copper Tubing	Coppe
						vord "heat.	Located on the box label, directly above the word "heat."	bel, directl	the box la	Located on	Brazing Rings	Brazir
					(60)	ox quantity.	Six digit no. located on the box label under box quantity.	n the box l	. located o	Six digit no	Flare Nuts	Flan
	20060667	E-RING					ımbers	Distinguishing Traceablity Numbers	uishing Tra	Disting		
	N/A	901-10-1/4	90						10		Order Qty	Orde
	No(s)	ישטויבוינים	0		ררכ	devices, LLC	1		399337	35	Order No.	Ord
	Heat Lot/Traceability	Component(s)	- Car			on troi			901-10-1/4-R	901-:	Part No.	Par