Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PRO
				V					ting	6 Meeting			
				1					ing	5 Training			
			400	-	7	45>	6m	1-23-16	0				
	2 S	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	 Mainter Tooling 			
			nspection Record	First Part Ir					Down Time Codes	Dow	ıctions	Special Notes / Instructions	Specia
													ROUTING:
	Ţ			i.									
										•			
		1	\ \!\										
			1										
			. 25										
									-				
													12
	0							0	0		37min	44	1/22/11
Scrap Code	Scrap	ω	Notes		1,000	Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/onis					-		1113				
		Thru-		Pcs./Hr			Cycle	Ö	Setup			Mach. No.	
									ceability.	quire trac	Do not require traceability.	Caps/Plugs	Caps
							-	Located on the bag followed by "Lot Number."	followed by	n the bag	Located o	Snap Rings	Snap
					1		box label.	Use their work order number and date on the box label.	er number ar	work ord	Use their	Flare Tubes	Flare
					+1+		etter "M."	Located on the spool label, starting with the letter "M."	ol label, start	n the spo	Located o	Copper Tubing	Coppe
							vord "heat."	Located on the box label, directly above the word "heat."	(label, direct	n the box	Located o	Brazing Rings	Brazir
			BRZ00				ox quantity.	Six digit no. located on the box label under box quantity.	d on the box l	o. located	Six digit n	Flare Nuts	Flan
			CASC-13	_				umbers	Distinguishing Traceablity Numbers	guishing i	Distin		
	8	397959	ASC-13							10		Order Qty	Ord
		No(s)	Component(s)	Cor		LLC	devices, LLC	THE STATE OF THE S		397959	10	Order No.	Ord
	bility	Heat Lot/Traceability		2			200			ASC-13-9	Α	Part No.	Par