BRAZING PF					Speci	KOOTING:	POLITING									14/	Date			Сар	Sna	Flar	Copp	Brazi	Fla		Orc	Orc	Pa
ODUCTION REC					Special Notes / Instructions											50	Emp. Name	Mach. No.		Caps/Plugs	Snap Rings	Flare Tubes	Copper Tubing	Brazing Rings	Flare Nuts		Order Qty	Order No.	Part No.
BRAZING PRODUCTION RECORD					uctions						s i						Prod Hrs.			Do not req	Located on	Use their v	Located on	Located on	Six digit no	Disting		3	
-	6 Meeting		3 Setup	 Maintenance Tooling 	Down Time Codes		-									30	Total Pcs.			Do not require traceability.	Located on the bag followed by "Lot Number."	Use their work order number and date on the box label.	Located on the spool label, starting with the letter "M."	Located on the box label, directly above the word "heat."	Six digit no. located on the box label under box quantity.	Distinguishing Traceablity Numbers	20	395547	JZ-K
					Codes												Cum	Hrs.	Cotun			ber and c	d, starting	directly a	e box labe	olity Numl			
				Date Part Submitted								1					Cum. Total				t Number	late on th	with the	bove the	el under b	pers		1	
				Time Of Day	THE PARTY												Down Time	Time	Cuelo			e box label.	letter "M."	word "heat."	ox quantity.			devices, LLC	natral
				Approved Yes / No	1000												Down Time Code											LLC	
		Check F																											
				Rev Letter	First Part Ir													Pcs./Hr	Selection of							1000			
				Inspector	Inspection Record				_								Notes									J-RING	J2	omponent(s)	
								1	J.	77	7							put/8hrs	Than							30			Heat Lo
				Notes															STATE OF THE PARTY							20140766	NIN	No(s)	Heat Lot/Traceability
Test I								P									Scrap		Section of the last	L									ty
Test Form 11/4/15																	Scrap Code												