										Meeting	6		
						,					4.7		
		Cath.	文十 (数)			UKS	BM	11/2/11			3		
	Sē	Notes	Inspector		Check	Approved Yes / No	Time Of Day	Date Part Submitted		MaintenanceTooling	2 1		
			First Part Inspection Record	First Part In					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
												v	ROUTING:
1													
	7												
5	1100								•				
1	7												
1													
			L										
											ti		
											A.S.		1
								SO MIN	(10	Smin	B	11/9/15
Scrap	Scrap		Notes		- О	Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
元 一 一		put/snrs					illie		1119.				
		Thru-		Pcs./Hr		31	Cycle		Setup			Mach. No.	
					_				, Y	Do not require traceability.	Do not requ	Caps/Plugs	Caps
			•				· a	ot Number	ved by "L	Located on the bag followed by "Lot Number."	Located on t		Snap
							e box label.	date on the	nber and	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
			×				etter "M."	g with the I	el, startin	Located on the spool label, starting with the letter "M."	Located on t	Copper Tubing	Coppe
							vord "heat.'	above the v	directly	Located on the box label, directly above the word "heat."	Located on t	Brazing Rings	Brazin
			BRZ03				ox quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
			CUTU-0-1/2	CU				nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
			SF403-2-3/16	SF4				1		10		Order Qty	Orde
	-	No(s)	component(s)	- com		LLC	devices, LLC	4		389764	38	Order No.	Orde
	bility	Heat Lot/Traceability								J#UJ-2-3/ 10	0700		rait ivo.