								(l			
			V					Training Meeting				
	M.	#	N	<	yas	6:2	2-11-16	R b				
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	1 Ma 2 Too			
		First Part Inspection Record	First Part I					Down Time Codes		structions	Special Notes / Instructions	Specia
-	-											ROUTING:
	*											
	0,0	-										
	52											
$\frac{1}{1}$												
-						17						
						8	_		35m2	2	70	11/01
Scrap Code	Scrap	Notes		п	Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs. To	1	Emp. Name	Date
	payonis				Spring Clarification			LE CONTRACTOR DE LA CON			The state of the s	
	Thru-		Pcs./Hr			Cycle	· 5	Setup Hrs.		<u>ō</u>	Mach. No.	
								aceability.	Do not require traceability.	Do n	Caps/Plugs	Сар
						. =	"Lot Number	Located on the bag followed by "Lot Number."	ited on the b	Loca	Snap Rings	Sna
						e box label.	nd date on the	Use their work order number and date on the box label.	their work o	Use	Flare Tubes	Flare
		BRZ00				letter "M."	ting with the	Located on the spool label, starting with the letter "M."	ited on the s	Loca	Copper Tubing	Coppe
	CSW-10-1-1/2	CUTU-0-1-1/8	CL		-	word "heat.	ly above the v	Located on the box label, directly above the word "heat."	ited on the b	Loca	Brazing Rings	Brazi
1	4	BRZ22				ox quantity.	abel under b	Six digit no. located on the box label under box quantity.	digit no. locat	Six d	Flare Nuts	Flar
Z	いたいとは、いかい	CUTU-42-5/32	5				umbers	Distinguishing Traceablity Numbers	Distinguishin			
		9-2.5-34							1		Order Qty	Ord
	No(s)	Component(s)	60		ררכ	devices, LLC	T C		400154		Order No.	Orc
	Heat Lot/Traceability		,			200		1-0	37-2.3-34-42-0	_	1 011 140.	- 0