			•						6 Meeting			
	Notes	Inspector	Rev Letter	Check	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 			
		First Part Inspection Record	First Part I		N-E			Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
												ROUTING:
0												
5		,										
	5.0	1										
	5.	0/										
	1/14											
	. 11.0											
20												
						199						
									3			-
									CA		لسا	7118
Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs		Pcs./Hr			Time		Hrs.			Mach. No.	
Application of the	Thru-					Cvcle		Setup				
				_					Do not require traceability.	Do not requ	Caps/Plugs	Сар
						=	ot Number.	ed by "Lo	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
						box label.	date on the	ber and c	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	with the le	l, starting	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						ord "heat."	bove the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
		A-KF004				x quantity.	el under bo	box labe	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		DCN316-HT	D				bers	lity Numl	Distinguishing Traceablity Numbers	Distingu		
	309847	2203A-4-1/4-0	220						5		Order Qty	Ord
	No(s)	component(s)	cor		LLC	devices, LLC	7	•	400904	40	Order No.	Ord
-	Heat Lot/Traceability		2						4/T-4-HC027	2022	air iso.	Pd