Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 			
			First Part Inspection Record	First Part I				O III WOO	Codes	Down Time Codes	ctions	Special Notes / Instructions	Speci
													ROUTING:
	Ø	9											
		Si	9	Y [
		S	2				_				1		
		7/4											
										(42	
										00		578	2/6
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cui	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					Time		Hrs.			TAIR ASSESSMENT OF THE PARTY OF	
		Thru-		Pcs./Hr			Cycle	OF-	Setup			Mach. No.	
	L	31			_				Į Ž	Do not require traceability.	Do not requ	Caps/Plugs	Cap
								Lot Number.	ved by "l	Located on the bag followed by "Lot Number."	Located on		Sna
					1		box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
					1		etter "M."	ng with the l	el, startir	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
					ı		vord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
ě							ox quantity.	bel under bo	e box lat	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		NIA	G-RING					nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
		393842	702-8-3/16	7,						40		Order Qty	Ord
	j	No(s)	component(s)	6		LLC	devices, LLC	C C		399336	39	Order No.	Ord
	lity	Heat Lot/Traceability		2			2			702-8-3/16-R	702-8	Part No.	Pa