									5 Training 6 Meeting			
			c.	CLIECK	163/140		o de la companya de l					
	Notes	Inspector	Rev Letter	Mtrl	Approved	Time Of Day	Date Part Submitted		 Maintenance Tooling 			
		First Part Inspection Record	First Part I					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
		ı										
		5										
		650					ı					
		060										
	₩	1										
									0		SS	61/2
Scrap Code	Sci	Notes			Code	Down Time	Cum. Iotal	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
Scran	Martine of the Section of the Sectio	The second second	HOMEST STATES		Down Time)	10 10 10		1	
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
	7							×	Do not require traceability.	Do not requ	Caps/Plugs	Caps
						=	ot Number.	ed by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
						box label.	date on the	ber and	Use their work order number and date on the box label	Use their w	Flare Tubes	Flare
•						etter "M."	g with the l	l, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						ord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
						x quantity.	oel under bo	e box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
	N/A	L-RING					nbers	olity Nun	Distinguishing Traceablity Numbers	Distingu		
	98E10H	S403-3-1/4	Ş						10		Order Qty	Ord
	No(s)	Component(s)			LLC	devices, LLC	4		401307	40	Order No.	Ord
	Heat Lot/Traceability	anonont/ol	2				1		S403-3-1/4-R	5403	Part No.	Par