Test Form 11/4/15	Test Fo)RD	BRAZING PRODUCTION RECORD	RAZING PRC
									es.				
										3 Setup 4 FAIR			
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	.,,	 Maintenance Tooling 			
	A STATE OF		t Inspection Record	First Part In					Codes			Special Notes / Instructions	Specia
													ROUTING:
	ð	2											
	9	2/25											
		6											
				<									Œ
		\$											
		The state of the s		-									
			0	F									
			2	4									
			20										
		×.											
Scrap	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/oills				Section South	IIIIIe						
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
	L								Ty.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
							=	ot Number.	ved by "L	Located on the bag followed by "Lot Number."	Located on		Snap
			CP13				box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
			BRZ05		1		etter "M."	g with the h	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
			BRZ01		1	3	vord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	_	Brazin
			CUTU-14-1/4	CU			x quantity.	bel under bo	ne box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
			CUTU-3-1/2	CL				nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
			SF4-4-3							300		Order Qty	Orde
		No(s)	Component(s)	00		ררכ	devices, LLC			400721	40	Order No.	Orde
	litv	Heat Lot/Traceability					1			S4-4-3-14	S4-	Part No.	Par