										ORD	BRAZING PRODUCTION RECORD	RAZING PRO
								Meeting				
								ning p	4 FAIR			
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling				
		art Inspection Record	First Part I					Down Time Codes	Dov	uctions	Special Notes / Instructions	Specia
												ROUTING:
2												
	55	9										
	216											
								100			Ø.	12
Scrap Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs. C		Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr			Cycle Time	- 8	Setup Hrs.			Mach. No.	
								accapinty.	bo not redail a naccability.		000	
			5				Lot Number.	Located on the bag followed by "Lot Number."	ed on the ba	Locati	Cans/Plugs	Cans
						box label.	d date on the	Use their work order number and date on the box label.	heir work or	U Se ti	face lubes	Fldie
						etter "M."	ing with the l	Located on the spool label, starting with the letter "M."	ed on the sp	Locat	Copper Tubing	coppe
						vord "heat."	y above the v	Located on the box label, directly above the word "heat."	ed on the bo	Locat	Brazing Rings	Brazir
				L		ox quantity.	abel under bo	Six digit no. located on the box label under box quantity.	git no. locate	Six dig	Flare Nuts	Flar
	N/A	L-RING					mbers	Distinguishing Traceablity Numbers	istinguishing	Di		
	392139	F							6		Order Qty	Ord
	No(s)	Component(s)	60		LLC	devices, LLC	T T		398943		Order No.	Ord
itv	Heat Lot/Traceability								L1-R		Part No.	Pai