BRAZING PRODUCTION RECORD			Special No	ROUTING:								2			Z.	Caps/Plugs	Snap Rings	Flare Tubes	Copper Tubing	Brazing Rings	Flare Nuts		Order Qty	Order No.	
CTION RECO			Special Notes / Instructions						*3			00	Emp. Name		Mach. No.	ugs	ngs	bes	bing	lings	uts		lty	lo.	
)RD			ctions							20			Prod Hrs.	THE REAL PROPERTY.		Do not req	Located or	Use their v	Located or	Located or	Six digit no	Disting		3	1001
	4 FAIR 5 Training 6 Meeting									ı		ō	Total Pcs.			Do not require traceability.	Located on the bag followed by "Lot Number."	Use their work order number and date on the box label.	Located on the spool label, starting with the letter "M."	Located on the box label, directly above the word "heat."	Six digit no. located on the box label under box quantity.	Distinguishing Traceablity Numbers	10	396777	100.000/10:
													Cum		Setup Hrs.	,	ed by "Lo	ber and o	ا, starting	directly a	e box lab	lity Numl			
		Date Part Submitted											Cum. Total				t Number	date on th	with the	bove the	el under b	bers		1	į
		Time Of Day											Down Time	THE PERSON NAMED IN	Cycle Time		r."	e box label.	letter "M."	word "heat.'	ox quantity.			devices, LLC	control
		Approved Yes / No											Down Time Code	AND DESCRIPTION										LLC	
		Mtrl Check																	-						
			First Part In											School Supplement	Pcs./Hr								130	Con)
		Inspector	Inspection Record			_	-						Notes									A-RING	1304-30-5/16-R	omponent(s)	
						25	3	5					la:		Thru- put/8hrs							ع د	ور		Heat Lo
		Notes														*						20293300	396762	No(s)	Heat Lot/ I raceability
					P								Scrap	The second second											IIITY
													Scrap Code												