Test Form 11/4/15)RD	BRAZING PRODUCTION RECORD	BRAZING PRO
				•									
										3 Setup 4 FAIR			
Notes			Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted					
The state of the s			Inspection Record	First Part In				Marin Marin	Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
													ROUTING:
Q V													
55.		_											
P													
5													
	1												
	ı l			1.2							1		
	- 1												
	- 1												
	1												
	1 1									1		98	1-15
Scrap			Notes			Down Time Code	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
					-		MCSHDQQQQW	And Appropriate	, ·	Do not require traceability.	Do not requ	Caps/Plugs	Caps
	1						* =	ot Number.	ed by "L	Located on the bag followed by "Lot Number."	Located on		Snap
	1						box label.	date on the	ber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
	l I						etter "M."	g with the le	l, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Copper
	1				3		ord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazin
NIA	~		C-RING				x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
NA	200		C35					bers	olity Num	Distinguishing Traceablity Numbers	Distingu		
2/2	- 1		1103-18-5/16	110						1		Order Qty	Orde
No(s)	rounne or		Component(s)	Con		LLC	devices, LLC			397049	39	Order No.	Orde
Heat Lot/Traceability		Heat Lo		,						1103-18-5/16-35	1103-1	Part No.	Par