Test Form 11/4/15	Test										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										5 Training6 Meeting			
					0.00								
	Notes		Inspector	Rev Letter	Mtrl Check	Approved	Time Of Day	Date Part Submitted	ance	 Maintenance Tooling 			
			Inspection Record	First Part Ir	THE REAL				Down Time Codes	Down Ti	ictions	Special Notes / Instructions	Specia
	1												ROUTING:
	Y												
	222												
	9								+				
				×									
			,										
									-	-			
			8							I.		S)	05/1
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total		Total Pcs	Prod Hrs.	Emp. Name	Date
		Thru- put/8hrs		Pcs./Hr			Cycle Time	, p	Setup Hrs.			Mach. No.	
	The state of the s		Spinishers Associated	Appropriate particular and the second	BOOK STATE OF THE PERSON OF TH	STANDARD STANDARD	STATE OF STATE OF STATE OF	のできる のできる	SECONDIFICATION OF THE PERSON	を のの ののの ののの	A Property of the	THE OWN PARTY.	
									bility.	Do not require traceability.	Do not req	Caps/Plugs	Caps
							п	Located on the bag followed by "Lot Number."	llowed by	the bag for	Located on	Snap Rings	Snap
							box label.	Use their work order number and date on the box label	าumber ar	ork order r	Use their w	Flare Tubes	Flare
							etter "M."	Located on the spool label, starting with the letter "M."	label, star	the spool I	Located on	Copper Tubing	Coppe
	2					1	vord "heat."	Located on the box label, directly above the word "heat."	bel, direct	the box lat	Located on	Brazing Rings	Brazir
	20060667	2001	E-RING				ox quantity.	Six digit no. located on the box label under box quantity.	າ the box	. located or	Six digit no	Flare Nuts	Flan
	CA	7	E12					umbers	ceablity N	Distinguishing Traceablity Numbers	Disting		
	397566	39	901-8-3/16	90						4		Order Qty	Orde
	No(s)	7	Component(s)	Con		LLC	devices, LLC	£		397541	35	Order No.	Ord
	Heat Lot/Traceability	Heat Lot,	nonet(c)				200			901-8-3/16-12	901-8	Part No.	Par