			1				Meeting	6		
		_	I				Training	7 1		
	STATE OF STA	St.	^		200	のカイス		ω		
is.	Notes	Inspector	Rev Le	Approved Mtrl Yes / No Check	Time Of Day	Date Part Submitted	Maintenance Tooling	2 1		
		art Inspection Record	First Part I			H			Special Notes / Instructions	Special
										ROUTING:
5										
		(
		5.5	1							
		/	-							
								1		
	\									
1	3 pcs	are to the	MADE &	and was	8	0	V	35m10	OTC	017/15
Code				code	T	•	J	3		
Scrap Scrap		Notes		Down Time	Down Time Do	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs				IIme	3.				
	Thru-		Pcs./Hr		Cycle	Setup	Se		Mach. No.	
							Do not require traceability.	Do not requ	Caps/Plugs	Caps
					-	y "Lot Number	Located on the bag followed by "Lot Number."	Located on	Snap Kings	aleuc
		CP13			e box label.	and date on the	Use their work order number and date on the box label.	Use their wo	Fidire Tubes	ridie
		BRZ04			etter "M."	rting with the I	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	coppe
1		BRZ01			word "heat."	ctly above the v	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazıı
		CUTU-14-3/16	5		ox quantity.	x label under bo	Six digit no. located on the box label under box quantity.	Six digit no.		Flar
		CUTU-3-1/2	0			Numbers	Distinguishing Traceablity Numbers	Distingu		
	た ち ロ ロ か と な	SF4-3-6					2		Order Qty	Ord
, and a second	No(s)	Component(s)	6	Ω	devices, LLC	T T	394493	39	Order No.	Ord
shility	TPAT OT/ PACES					ı				