										200		
									6 Meeting	<b></b>		
										n h '		
	Notes	Inspector		Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	(0	<ol> <li>Maintenance</li> <li>Tooling</li> <li>Setun</li> </ol>	(a) Ky		
		Inspection Record	First Part In					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
X												
	798 N		8									
						1						
+				$\top$								
									20		SS	122
Scrap Scrap	Sc	Notes			Down Time Code	Down Time	Cum. Total	Cu	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs	CAMPA	/100			Time		Hrs.				
	Thru-		Pcs./Hr		The state of the s	Cycle		Setup			Mach. No.	
								ţ.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
1							Lot Number.	wed by "	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
						box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
				, ,		etter "M."	ng with the I	el, starti	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						vord "heat."	above the v	, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazin
			1			ox quantity.	bel under bo	ne box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
	30060667	E-RING					mbers	blity Nu	Distinguishing Traceablity Numbers	Distingu		
	N/N	E8							20		Order Qty	Orde
	No(s)	Component(s)	Con		ררכ	devices, LLC	4		397820	39	Order No.	Ord
	Heat Lot/Traceability		)			7			F8-X	-	י מונושט.	rai