Test Form 11/4/15	Test F)RD	BRAZING PRODUCTION RECORD	BRAZING PRO
									Meeting			
									FAIR	4 12		
									Setup	3		
	.30	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2		
			rt Inspection Record	First Part In					Down Time Codes		Special Notes / Instructions	Specia
	3											ROUTING:
	7											
		720	5						+			
		1										
		5										
	l											
					_				00		58	12/17
Scrap	Scrap		Notes		NACT .	Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					Time		Hrs.			
		Thru-		Pcs./Hr			Cycle	ā	Setup		Mach. No.	
									Do not require traceability.	Do not requi	Caps/Plugs	Caps
								"Lot Number.	Located on the bag followed by "Lot Number."	Located on t	Snap Rings	Snap
							box label.	nd date on the	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
							etter "M."	ting with the I	_ocated on the spool label, starting with the letter "M."	Located on th	Copper Tubing	Coppe
						<u> </u>	vord "heat.'	ly above the v	Located on the box label, directly above the word "heat."	Located on th	Brazing Rings	Brazir
							ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. l	Flare Nuts	Flan
		2/2	C-RING	*				umbers	Distinguishing Traceablity Numbers	Distinguis		
		2/4	C-15		W				3	8	Order Qty	Ord
		No(s)	Component(s)	Con		ררכ	devices, LLC	H	481	394481	Order No.	Ord
	ilitv	Heat Lot/Traceability							C15-R	CI	Part No.	Par