Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
											34		
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Ф	 Maintenance Tooling 			
			Inspection Record	First Part In					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
	Č												ROUTING:
	7												
	>												
		7,7	11										
		5	1./.										
				ik'									
			Ž										
										6		000	130
Code						Coac				4			12/2
Scrap	Scrap		Notes			Down Time	Down Time	Cum. Total	Cu	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8nrs					ilme		nrs.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
									A CONTRACTOR OF THE PERSON NAMED IN CONT				The second second
								83	ty.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
							1	Lot Number.	wed by "I	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
					L		box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
							etter "M."	ng with the l	el, startir	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
					.		vord "heat."	above the w	, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
							x quantity.	bel under bo	າe box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
		PO1151104	L-RING					mbers	blity Nur	Distinguishing Traceablity Numbers	Distingu		
		N/A	5							6		Order Qty	Orde
	ą	No(s)	Component(s)	Co		LLC	devices, LLC	C C		395432	39	Order No.	Ord
	lity	Heat Lot/Traceability		2			ont not			L5-R	_	Part No.	Par