	1									RD	BRAZING PRODUCTION RECORD	BRAZING PRO
									Meeting	6		
	1								FAIR	4 10		
									Setup	. ω		
		Notes	inspector		Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2		
			Inspection Record	First Part In					Down Time Codes	tions	Special Notes / Instructions	Specia
												100
	?											ROUTING:
	Z											
	>											
		1										
		7,7	1,									
		50.	()									
		7										
		ラン、										
		5										
1		\										
1												
									نو		SB	12/30
Scrap	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					Time	9.	_ nis.			
	De jacob	Thru-		Pcs./Hr			Cycle	, h	Setup		Mach. No.	
		4										
			ľ						Do not require traceability.	Do not requir	Caps/Plugs	Caps
->							П	/ "Lot Number	Located on the bag followed by "Lot Number."	Located on th	Snap Rings	Snap
		-					e box label.	nd date on the	Use their work order number and date on the box label	Use their wor	Flare Tubes	Flare
							etter "M."	rting with the	Located on the spool label, starting with the letter "M."	Located on th	Copper Tubing	Coppe
						-	word "heat.	tly above the v	Located on the box label, directly above the word "heat."	Located on th	Brazing Rings	Brazir
		2/2	A-KF005	,			ox quantity.	label under b	Six digit no. located on the box label under box quantity.	Six digit no. lo	Flare Nuts	Flan
		NA	DCN316-HT	DC				lumbers	Distinguishing Traceablity Numbers	Distinguis		
		394365	2201-7-1/4-0	220					2	2	Order Qty	Ord
-		No(s)	Component(s)	Con		LLC	devices, LLC	4	435	395435	Order No.	Ord
	lity	Heat Lot/Traceability		,			7	J	7-1/4	2201-7-1/4	Part No.	Par

Test Form 11/4/15