Test Form 11/4/15	Test Fo										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
	5	Notes	Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted		2 Tooling 3 Setup			
			First Part Inspection Record	First Part I					Codes			Special Notes / Instructions	Specia
	,												ROUTING:
	7												
		2											
		2											
	2												_
							65.00						
										W		SB	1/7
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					Time		Hrs.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
		4							, ×	Do not require traceability.	Do not requ	Caps/Plugs	Caps
					•			ot Number.	ed by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
					to .		box label.	date on the	ber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
							etter "M."	g with the k	d, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
							ord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
							x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		N/A	C-RING					nbers	olity Num	Distinguishing Traceablity Numbers	Distingu		
		Z/A	C-15							3		Order Qty	Ord
		No(s)	Component(s)	S		LLC	devices, LLC	4		396225	39	Order No.	Ord
	ility	Heat Lot/Traceability)						C15-R	0	Part No.	Pai