												BRAZING DRODINGTION BECORD	DO ATINIC DD
				Ų.						6 Meeting			
		dsc	*	pi	<	Ligh	SAA	2-1-16		4 FAIR			
	Notes	0	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted					
			rt Inspection Record	First Part I					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
1	D												
	2	30	9										
	4	26											
									1				
	0		times (Dommons)	The same of	recomparts mutti	1/9	20 min		200	200	62	20	170916
	POLICE TO SERVING	ment story	5 multiple frames	ACM OWNER	11.24 to 1		20 min	1877				基礎	100.16
Scrap Scrap Code	Sc		Notes			Down Time Code	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs	3	Pcs./Hr			Time		Hrs.			Mach. No.	
							-		2		And Address of the	STATE OF STA	
									·Ý	Do not require traceability.	Do not requ	Caps/Plugs	Cap
							-	ot Number.	ved by "Lo	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snai
			CP13				box label.	date on the	nber and o	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
			BRZ05				etter "M."	g with the l	ર્ગ, starting	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
			BRZ01				vord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
			CUTU-14-1/4	CU			ox quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
			CUTU-3-1/2	כנ				bers	blity Num	Distinguishing Traceablity Numbers	Distingu		
			SF4-4-4							50		Order Qty	Ord
	No(s)		Component(s)	Cor		LLC	devices, LLC	THE STATE OF THE S		398751	39	Order No.	Ord
	Heat Lot/Traceability	Heat L					1			S4-4-4-14	S4-	Part No.	Pa