Test Form 11/4/15	Test										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										4 FAIR 5 Training			
										3 Setup			
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	.5	 Maintenance Tooling 			
			Inspection Record	First Part I					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	Z												
		7 5											
		7.10											
		13.0											
	:												
				-									
										ప		Sô	1/29
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs		PCS./ FIT			Time		Hrs.	Appropriate Approp		IVIACH. NO.	
	j	Thru-		Doc /Ur			Cycle		Setup			Mach No	
									, Y	Do not require traceability.	Do not requ	Caps/Plugs	Caps
								ot Number.	ved by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
							box label.	date on the	nber and	Use their work order number and date on the box label	Use their w	Flare Tubes	Flare
							etter "M."	g with the l	श, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
							vord "heat."	above the v	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
							ox quantity.	ວel under bc	e box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
		N/A	C-RING					nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
		NIA	C20		nc					3		Order Qty	Orde
	3	No(s)	Component(s)	Cor		LLC	devices, LLC	H		398704	39	Order No.	Ord
	lity	Heat Lot/Traceability					200	ı		C20-R	0	Part No.	Par