						ı			
						6 Meeting			
		A10-0	9	\neg	9				
	Notes	Rev Letter Inspector	Yes / No Check	ed Time Of Day	Submitted	2 Tooling 3 Setup			
		First Part Inspection Record	-11	MATTER AND	Codes	Down Time		Special Notes / Instructions	Speci
							i i		ROUTING:
Ž									
?									
								-	
	. S.	6							
	7								
	9,10								
				~					7 41 7
				Š	-		2	しい	2/8/11
Scrap Scrap	en e	Notes	Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8nrs			lime	nrs.				
	Thru-	Pcs./Hr		Cycle	Setup			Mach. No.	
	ď					Do not require traceability.	Do not requ	Caps/Plugs	Сар
	ie e			er."	by "Lot Numb	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
	2012/07/06	J-RING		the box label.	er and date on t	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
	N/A	JR4		e letter "M."	starting with th	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
		BRZ07		e word "heat."	rectly above th	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
		FLR-5/8		box quantity.	ox label under	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		CFT-5/8			y Numbers	Distinguishing Traceablity Numbers	Distingu		
	10/10	SF504-8-3/161/2				1		Order Qty	Ord
	No(s)	component(s)	rc	devices, LLC	1	399758	39	Order No.	Ord
4	Heat Lot/Traceability	Component(s)				F5U4-8-5/ 101/ 24	F304-0-	rait No.	Ра