									6 Meeting	6 (1)		
- 1												
1 6	Control Month	30000 - Control		Check	Yes / No		Submitted		2 Tooling 3 Setup	3 2		
S	Notes	Inspector	Rev Letter	Mtrl	Approved	Time Of Day	Date Part		1 Maintenance			
		t Inspection Record	First Part Ir					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
1 1												ROUTING:
-												
\rightarrow												
-												
-	5,	7										
+	N.V.											
_												
+												
+	7											
+												
-												
-												
+												
+							+		نو		SB	3/4
		Notes			Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
										OUR MANAGEMENT		
								<i>'</i> .	Do not require traceability.	o not requ	Caps/Plugs [Caps
						=	t Number.'	ed by "Lo	Located on the bag followed by "Lot Number."	ocated on i	Snap Rings	Snap
						box label.	date on the	ber and d	Use their work order number and date on the box label.	Jse their wo	Flare Tubes	Flare
						etter "M."	with the le	, starting	Located on the spool label, starting with the letter "M."	ocated on t	Copper Tubing L	Coppe
			11			ord "heat."	bove the w	directly al	Located on the box label, directly above the word "heat."	ocated on t	Brazing Rings L	Brazir
i .						x quantity.	el under bo	box labe	Six digit no. located on the box label under box quantity.	six digit no.	Flare Nuts	Flan
ı I	NIA	G-RING					bers	lity Numb	Distinguishing Traceablity Numbers	Distingu		
	N/A	GR3	×	,					12		Order Qty	Ord
	No(s)	Component(s)	Coll		LC	devices, LLC	7		399365	39	Order No.	Ord
\mathbf{z}	Heat Lot/ Iraceability	nonen+(c)				óntrol			מהטיהו	2	י מוניאס.	Pai