											CONTRACTOR	
								ting	6 Meeting			
								in C	4 FAIR			
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2 Tooling			
		First Part Inspection Record	First Part In					Down Time Codes		ıctions	Special Notes / Instructions	Specia
												ROUTING:
3												
	100											
	2000	4										
	3											
				1								M
6	OF 150	120 OF	7000				100					1
_	U	CARBASE VALL	- In	CAND DE RE			9	O COMPANY	2/0	N	476	7
- 1	SONLY	DASE PARTS	!	THE TOTAL					1 . 10 % . Dare 1 110	7	1	111
code		י						N	J	N	170	2
Scrap Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs. Cu		Prod Hrs.	Emp. Name	Date
	put/8hrs					Time		nrs.				
	Thru-		Pcs./Hr			Cycle	-	Setup			Mach. No.	
		CP13						ceability.	Do not require traceability.	Do not	Caps/Plugs	Cap
		L-RING				-	Lot Number	Located on the bag followed by "Lot Number."	on the ba	Located	Snap Rings	Snaj
		CUTU-0-3/16	CU			box label.	d date on the	Use their work order number and date on the box label.	ir work ord	Use the	Flare Tubes	Flare
		BRZ04				etter "M."	ng with the I	ocated on the spool label, starting with the letter "M."	on the sp	Located	Copper Tubing	Coppe
		BRZ03				vord "heat."	above the v	ocated on the box label, directly above the word "heat."	on the bo	Located	Brazing Rings	Brazi
		CUTU-0-1/2	19 CI			ox quantity.	abel under bo	Six digit no. located on the box label under box quantity.	t no. locate	Six digit	Flare Nuts	Flar
	(L3/4		_			mbers	Distinguishing Traceablity Numbers	inguishing	Dist		
	389860	SF403-2-3/16	∜ SF₄						150		Order Qty	Ord
	No(s)	Component(s)	Cor		ררכ	devices, LLC	H		389860		Order No.→	Ord
₹	Heat Lot/Traceability					1			0.00-0/ 100/ 11/			

: