		\										
		\						ľ				
	Notes	Inspector	Rev Letter	Check	Approved Yes / No YES	Time Of Day	Date Part Submitted 3-16-15		Maintenance Tooling Setup FAIR Training	л <b>д</b> з г 1		
		Part Inspection Record	First Part I					Codes			Special Notes / Instructions	Specia
					1							ROUTING:
9	5.55								٥			
			:			ge.						
	1											
			=									
									-			
Scrap	Sc	Notes			Down Time Code	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
								, ×	Do not require traceability.	Do not requ	Caps/Plugs	Caps
				<u> </u>		• "	ot Number	ved by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
				<u> </u>		e box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						letter "M."	g with the	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						word "heat."	above the v	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
		BRZ23				ox quantity.	el under b	ie box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
		CASC-3		8		500	nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
L		ASC-4					1		10		Order Qty	Orde
	No(s)	Component(s)	Cor		LC	devices, LLC	T.		404186	40	Order No.	Ord
	Heat Lot/Traceability		,						700-4-0	-		rait No.