Test Form 11/4/15	Test Fo											ORD	BRAZING PRODUCTION RECORD	BRAZING PRO
				1	, ,						4 FAIR 5 Training			
	***	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	***	 Maintenance Tooling 			
			ο.	First Part Inspection Record	First Part Ir					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
	1													ROUTING:
	Z	*												
	?	,												
	· ·	S,												
) 1	2												
											25		SS	1/22
Scrap Code	Scrap			Notes			Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Thru- put/8hrs	Jh.		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
		4			,					Ý	Do not require traceability.	Do not requ	Caps/Flugs	caps
			<u> </u>						it Number.	ed by "Lo	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
			L T					box label.	ate on the	ber and (Use their work order number and date on the box label	Use their w	Flare Tubes	Hare
			L T					etter M.	with the it	, starting	Located on the spool label, starting with the letter Wi	rocated on	copper lubing	coppe
			 					ord "heat."	bove the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
								x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
		32140766		J-RING					bers	olity Num	Distinguishing Traceablity Numbers	Distingu		
		N/A	_	J2							25		Order Qty	Orde
		No(s)		component(s)	Con		LLC	devices, LLC	F C		397825	39	Order No.	Ord
	ility	Heat Lot/Traceability	 		,			7			J2-R	ſ	Part No.	Par