Part No.	S404-8-3/16
Work Order No.	628249
Order Otv	40



Distinguishing Traceablity Numbers					
Flare Nuts	Six digit no. located on the box label under box quantity.				
Brazing Rings	Located on the box label, directly above the word "heat."				
Copper Tubing	Located on the spool label, starting with the letter "M."				
Flare Tubes	Use their work order number and date on the box label.				
Snap Rings	Located on the bag followed by "Lot Number."				
Caps/Plugs	Do not require traceability.				

Operations	Mach. No.	Setup Min	Cycle Time	Pcs/Hr	Thru-put/8 hrs	
MANUAL BRAZING		15	75 sec	48	345	
BRAZING WASH,RINSE, WATER TEST		0	60 sec	60	432	
PACK/REPORT/SNED TO MS-KF FG	·	0	3 sec	1425	10260	

Comp	oonent(s) (See BOM)	QTY	Heat Lot/Traceability No(s)
SF404-8-3/16	DIST, NOZZLE, FOR ASSY FLARE	1	
CUTU-1-1/2	1/2 COPPER TUBING, 1" LG .500 OD X .032 WALL	1	
BRZ23	BRAZE RING .047 DIA X .500 ID SIL-FOS 18 - NEED MTL CERTS	1	
CP13	PLUG, FOR 1/2 OD TUBE, PLASTIC IND COMPONENTS P/N TAP-T-3X	1	

u	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down Time	Down Time Code	Notes	Scrap	Scrap Code
l io										
1st Operation										
15										
	ROUTING:	1								
o										
ati										
iad										
2nd Operation										
	ROUTING:									
nc										
atic										
per									•	
3rd Operation			_				_			
310										

Special Notes / Instructions	Down Time Codes	First Part Inspection Record						
	1 Maintenance2 Tooling	Date Part Submitted	Time Of Day	Approved Yes / No	Rev Letter	Material Check	Inspector	Notes
	3 Setup							
	4 FAIR5 Training							
	6 Meeting							