										1857.			
											(n N		
	Notes		Inspector	Rev Letter	Check	Approved Yes / No	Time Of Day	Date Part Submitted	ro	 Maintenance Tooling Setup 	(n N :		
			t Inspection Record	First Part Ir					Codes	Down Time	tions	Special Notes / Instructions	Specia
													ROUTING:
	2												
		5	9										
		, ,											
		5											
	1												
				2									
										-		SB	12/3
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cui	Total Pcs.	Prod Hrs.	Emp. Name	Date
100		put/8hrs		,			Time		Hrs.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
									ţy.	Do not require traceability.	Oo not requ	Caps/Plugs [Caps
							a	ot Number.	wed by "L	Located on the bag followed by "Lot Number."	ocated on		Snap
							box label.	date on the	nber and	Use their work order number and date on the box label.	Jse their wo	Flare Tubes	Flare
							etter "M."	ng with the l	el, startin	Located on the spool label, starting with the letter "M."	ocated on	Copper Tubing	Coppe
						a:	vord "heat."	above the w	, directly	Located on the box label, directly above the word "heat."	ocated on	Brazing Rings	Brazin
					_		ox quantity.	bel under bo	ne box lak	Six digit no. located on the box label under box quantity.	six digit no.	Flare Nuts	Flare
	AAA	2	C-RING					nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
	ZA	7	C-15							1		Order Qty	Orde
	No(s)	-	Component(s)	G G		LLC	devices, LLC	H		392699	39	Order No.	Orde
	Heat Lot/ I raceability	Heat Lot,		,			1			CTUTY	•		. 01.01.00