						Meeting	o (		
	d 63	C 21	1	1.30- 4	1273-15		υ 4 π		
	Notes	Rev Letter Inspector	Mtrl Check	Time Of Day	Date Part Submitted		2 1		
		First Part Inspection Record				Down Time Codes	ctions	Special Notes / Instructions	Specia
			-						ROUTING:
2									
								•	
			+						
	-								
Scrap		Notes	Down Time Code	Down Time Co	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs	Pcs./Hr		Cycle Time	s. up	Hrs.		Mach. No.	
								Contract of the Contract of th	
						Do not require traceability.	Do not requ	Caps/Plugs	Cap
				=	y "Lot Number.	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
				box label.	ind date on the	Use their work order number and date on the box label	Use their w	Flare Tubes	Flan
				etter "M."	rting with the l	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
1		CP13		ord "heat."	tly above the w	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
		BRZ03		ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Fla
		CUTU-1-1/2			Numbers	Distinguishing Traceablity Numbers	Distingu		
		SF403-3-1/4				10		Order Qty	Orc
,	No(s)	Component(s)		devices, LLC		395109	39	Order No.	Orc.
7	Heat Lot/Traceability			O T T T T T T T T T T T T T T T T T T T		CONTRACTOR OF THE PARTY OF THE			