										4 7		
	Notes	Inspector	Nev Letter	Check	Yes / No	- Day	Submitted			3 2		
	**************************************		Postottor	Mtrl	Approved	Timo Of Day	Date Part	נט	1 Maintenance			
		rt Inspection Record	First Part I					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
	Z											
	, 0										1	
	55 CF -											
			15									
									51		SB	1/22
Scrap Code	Scrap	Notes			Down Time Code	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs					lime		Hrs.				
	Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
								ty.	Do not require traceability.	Do not requ	Caps/Plugs	Cap
						=	ot Number.	wed by "L	Located on the bag followed by "Lot Number."	Located on		Sna
						box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	g with the le	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						vord "heat."	above the w	, directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
	N/N	G-RING				x quantity.	el under bo	ne box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
	NA	G3					bers	blity Nur	Distinguishing Traceablity Numbers	Distingu		
	NA	702-9-3/16	7.						51		Order Qty	Ord
	No(s)	component(s)	6		LLC	devices, LLC	1		397795	39	Order No.	Ord
	Heat Lot/Traceability)			on tool	ı		/02-9-3/16-3	702-5	Fait No.	Fd