										6 Meeting	6		
											4 1		
											3		
n e		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 	N I		
			rt Inspection Record	First Part In					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
													ROUTING:
	9	is .											
	X.												
		_											
		こくでじ											
	1												
		7 5											
		1											
													26
					1								
										36		SB	12/10
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					Time		Hrs.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
	The second second second		The second of th	IS COMPANY		on complete property							- (A60
		*							1.	Do not require traceability.	Oo not requ	h	Caps
		ā					1	ot Number.	ed by "Lc	Located on the bag followed by "Lot Number."	ocated on t	Snap Rings	Snap
							box label.	date on the	ber and c	Use their work order number and date on the box label.	Jse their wo	Flare Tubes	Flare
			Q.				etter "M."	with the I	l, starting	Located on the spool label, starting with the letter "M."	ocated on t	Copper Tubing	Coppe
							vord "heat."	bove the v	directly a	Located on the box label, directly above the word "heat."	ocated on 1	Brazing Rings	Brazin
							ox quantity.	el under bo	e box labe	Six digit no. located on the box label under box quantity.	six digit no.	Flare Nuts	Flare
		P01151106	L-RING	-				bers	lity Num	Distinguishing Traceablity Numbers	Distingu		
10		393278	S403-6-3/16	S40						25		Order Qty	Orde
		No(s)	component(s)	com		LLC	devices, LLC	THE STATE OF		393398	39:	Order No.	Orde
	lity	Heat Lot/Traceability		2			on tool			S403-6-3/16-R	S403-6	Part No.	Par