Notes Notes Scrap Scrap Code Scrap First Part Inspection Record Rev Letter Inspector Notes Notes Notes Test Form 11/4/15	Approved Mtrl Rev Le	Time Of Day	Codes Date Part Submitted	Down Time I Maintenance 2 Tooling 3 Setup 4 FAIR 5 Training 6 Meeting		TING: Special Notes / Instructions	ROUTING:
Notes Scrap Notes Notes Notes Notes Notes Notes	Mtrl	Time Of Day	Codes	Down Time Maintenance Tooling Setup FAIR		cial Notes / Instru	ROUTING
Notes Scrap Notes Scrap	MAX.		Codes	Down Time		a:	ROUTING
Notes Scrap							ROUTING
Notes Scrap							
Notes Scrap							
Notes Scrap							
Notes Scrap							
Notes Scrap							
Notes Scrap							
Notes Scrap							
Notes Scrap							
. Thru-put/8hrs Scrap							
Thru- put/8hrs Notes Scrap					(5mis		1.
. Put/8hrs Scrap		Ø	6	1	30	ر د	12/29
Thru- put/8hrs	Down Time Code	Down Time Do	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Time	Hrs.			Mach. No.	
	Pcs./	Cycle	Setup				
				Do not require traceability.	Do not requi		Сар
		ber."	Located on the bag followed by "Lot Number."	the bag followe	Located on t		Sna
CP13		the box label.	Use their work order number and date on the box label.	ork order numb	Use their wo		Flare
BRZ03		he letter "M."	Located on the spool label, starting with the letter "M."	the spool label,	Located on t	- T	Coppe
CUTU-1-1/2		ne word "heat."	Located on the box label, directly above the word "heat."	the box label, d	Located on t	S	Brazii
L-RING		r box quantity.	Six digit no. located on the box label under box quantity.	located on the	Six digit no. I	Flare Nuts S	Flar
L1-1/2			ity Numbers	Distinguishing Traceablity Numbers	Distingui	1	
SF403-4-3/16 39540 (6		Order Otv	ord
Component(s) No(s)		devices, LLC	Ŧ	395401	395	Order No.	Ord
Heat Lot/Traceability		-		S403-4-3/16-1.5	\$403-4-3	Part No.	Par