										6 Meeting			
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	ance	 Maintenance Tooling 			
			Inspection Record	First Part Ir					me Codes	Down Time	ctions	Special Notes / Instructions	Special
													ROUTING:
	<u> </u>									9		S	1100
Code						Code				۷		ñ S	13/2
-	Scrap		Notes		ŝ.	Down Time	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					lime		Hrs.				
		Thru-		Pcs./Hr			Cycle	8	Setup			Mach. No.	
	(6)								oility.	uire traceat	Do not require traceability.	Caps/Plugs	Caps
							=	Located on the bag followed by "Lot Number."	llowed by '	the bag fo	Located on	Snap Rings	Snap
							box label.	Use their work order number and date on the box label.	number an	ork order r	Use their w	Flare Tubes	Flare
							etter "M."	Located on the spool label, starting with the letter "M."	abel, start	the spool I	Located on	Copper Tubing	Coppe
							vord "heat."	Located on the box label, directly above the word "heat."	oel, directl	the box lab	Located on	Brazing Rings	Brazin
							ox quantity.	Six digit no. located on the box label under box quantity.	the box la	. located or	Six digit no.	Flare Nuts	Flare
	30151504	3016	G-RING					mbers	ceablity Nu	Distinguishing Traceablity Numbers	Distingu		
	À	N/A	701-3-5/16	70						2		Order Qty	Orde
	No(s)	7	component(s)	Con		TC	devices, LLC	4		392856	35	Order No.	Orde
	Heat Lot/Traceability	Heat Lot,					2			/UT-3-3/ TO-K	-T0/	rait No.	FdI