BRAZING PRC		Special	ROUTING:				1/12/1	Date		Caps	Snap	Flare	Coppe	Brazin	2	Orde	Ord	Par
BRAZING PRODUCTION RECORD		Special Notes / Instructions					E	Emp. Name	Mach. No.	Caps/Plugs	Snap Rings	Flare Tubes	Copper Tubing	Brazing Rings		Order Qty	Order No.	Part No.
ORD	654321	ictions					HELISA	Prod Hrs.		Do not requ	Located on	Use their w	Located on	Located on	Distingu		39	AS
	Maintenance Tooling Setup FAIR Training Meeting	Down Time Codes					£ (0	Total Pcs.		Do not require traceability.	Located on the bag followed by "Lot Number."	Use their work order number and date on the box label.	Located on the spool label, starting with the letter "M."	Located on the box label, directly above the word "heat."	Distinguishing Traceablity Numbers	10	396553	ASC-7-4
	S	Codes					10	Cum. Total	Setup Hrs.	×	ved by "Lot	nber and da	el, starting w	directly abo	blity Numbe			
	Date Part Submitted 15/6	The Section									Number."	te on the k	ith the let	ove the wo	irs		THE COL	
	Time Of Day						13	Down Time	Cycle Time			ox label.	ter "M."	quantity.			devices, LLC	
	Approved Yes / No YES / NO							Down Time Code									LLC	
	Check Re	Fir																_
	and the same of th	First Part Insp							Pcs./Hr					, <u> </u>	CSW	A	Comp	,
	Inspector	Inspection Record					1	Notes						GP13	CSW-1-1/2	ASC-7	Component(s)	A (4.05)
	(C) nsp (D) nsp			+					Thru- put/8hrs							396		Heat L
	Notes			24	=											6563	No(s)	Heat Lot/Traceability
Test F			7	2			B	Scrap										ilitv
Test Form 11/4/15	7					1		Scrap Code										