Test Form 11/4/15	Test										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
			Action of the State of the Stat	新教教	TEN SE		(4) (1)			6 Meeting			
			and a		(16		100					
			The state of the s	1		VER	9:00	12-20-16			***		
	Notes	A STATE OF THE PARTY OF THE PAR	Inspector	Rev Letter	Check	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 			
			t Inspection Record	First Part In				A	Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	9												
	>												
		55											
		18											
	U												
	\												
				z		<							
							(
							3	とと			1 mallon	1	D5/D
Scrap	Scrap		Notes		ru .	Down Time Code	Down Time	Cum. Total	Сп	Total Pcs.	Prod Hrs.	Emp. Name	Date
はいいのかの		pur/onis		The second second			111110		111.9				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
						1000年間が1000円		10 THE TAX OF THE TAX	7.		000000000000000000000000000000000000000		
									< C	Do not require traceability	Do not regi		Cano
							a	ot Number	ved bv "I	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snar
							box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
							etter "M."	າg with the l	el, startir	ocated on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
			BRZ08				vord "heat."	above the v	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
			CFT- 5/8				οχ quantity.	bel under bo	e box lal	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
			FLR-5/8					nbers	blity Nur	Distinguishing Traceablity Numbers	Distingu		
	395383	326	SF5-3-8	,						50		Order Qty	Ord
	No(s)		component(s)	- Co		LLC	devices, LLC	THE STATE OF THE S		395383	39	Order No.	Ord
	Heat Lot/Traceability	Heat Lot		,						F5-3-8	 	Part No.	Par