	Specia	ROUTING:				2/12	Date		Caps	Snap	Flare	Brazii	Flar		Ord	Ord	Ра
	Special Notes / Instructions					5	Emp. Name	Mach. No.	Caps/Plugs	Snap Rings	Flare Tubes	Brazing Rings Copper Tubing	Flare Nuts		Order Qty	Order No.	Part No.
6 5 4 3 2 1 A							Prod Hrs.		Do not requ	Located on	Use their w	Located on	Six digit no.	Distingu		40	1001
							Total Pcs.		Do not require traceability.	Located on the bag followed by "Lot Number."	Use their work order number and date on the box label.	Located on the box label, directly above the word "heat."	Six digit no. located on the box label under box quantity.	Distinguishing Traceablity Numbers	7	400354	. 00 = 0/ = 0 =/ =0
	Codes						Cun	Setup Hrs.	¥.	ved by "Lo	ber and	directly a	e box lab	blity Num			
Date Part Submitted							Cum. Total			ot Number	date on th	above the	el under b	bers		Ŧ	
Time Of Day							Down Time	Cycle Time		· =	e box label.	word "heat.'	ox quantity.		2	devices, LLC	1
Approved Yes / No							Down Time Code				ı					LLC	
Check P																	
Rev Letter	irst Part In							Pcs./Hr						7.1	703	Cor	)
Inspector	First Part Inspection Record		50	5			Notes						G-RING	65	03-2-5/16-1/2	Component(s)	
				1				Thru- put/8hrs									I Heat
Notes								-					4/14			No(s)	Heat Lot/Traceability
		0					Scrap									7111.69	7
							Scrap										